



13. Basket Storage

F. M. TALBOT
BASKET FAC.
AVERAGE 100 HANDS, NIGHT WATCHMAN & PORTABLE
CLOCK, 300' 72" HOSE ON REEL IN HALL, 150' 2" HOSE ATT.
TO 4 P.S. IN WALLS, F.R. BOX 1 BLOCK DISTANT, HEAT, LIVE
STEAM, FUEL, COAL, LIGHTS, NO LIGHTS IN PICKING HO.

ULRICH WAGON WKS.
NO WATCHMAN, NO HOSE, NO LIGHTS.
HEAT, STEAM, FUEL, COAL & WOOD.

MERGENTHEIM, STERNE and STROUSE,
PERU WOOLEN MILLS.
AVERAGE 100 HANDS, NIGHT WATCHMAN & PORTABLE
CLOCK, 300' 72" HOSE ON REEL IN HALL, 150' 2" HOSE ATT.
TO 4 P.S. IN WALLS, F.R. BOX 1 BLOCK DISTANT, HEAT, LIVE
STEAM, FUEL, COAL, LIGHTS, NO LIGHTS IN PICKING HO.

JAN. 1893
PERU
IND.

SMITH BROS.
FLOUR AND FEED MILL.
REDUCING
STATION.
2 SETS DOUBLE ROLLERS, 1 ROLL
STONE, 1 CENTRIFUGAL REEL,
2 SCRAPING REELS, 2 BOLTS,
1 RUCKWHEAT MARCH, 1 CONVEYER,
1 CORN MEAL BOLT,
1 CYCLONE DUST COLLECTOR,
TERRY DUST.

Scale of Feet.
50 40 30 20 10 0 50 100 150

TRIPPLICATE